


Why smoke spread so quickly

Workers were forced to evacuate the smoky World Trade Center in darkness and without instructions because the Feb. 26 bomb explosion knocked out communication, electrical and fire safety systems. Here's a look at what happened:



Source: National Fire Protection Association

By Marty Baumann, USA TODAY

USA TODAY · WEDNESDAY, MAY 26, 1993

NY, NY